

DELHI JAL BOARD: GOVT. OF NCT OF DELHI  
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)  
ROOM NO. 208, VARUNALAYA PHASE-I  
KAROL BAGH, NEW DELHI – 110005  
# 23558264

No./DJB/EE(RWH/GWC)/2019/1392

Dated:- 28/3/2019


To,

Manager,  
Nathu Ram Convent Sr. Sec. School,  
Shiv Ram Park, Phase-II, Nilothi More,  
Nangloi, Delhi-41

**Subject: Adequacy certificate in regard to rain water harvesting system at Nathu Ram Convent Sr. Sec. School, Shiv Ram Park, Phase-II, Nilothi More, Nangloi, Delhi-41.**

Please refer to your letter dated 03.10.2018, in which you have informed that Rain Water Harvesting has been installed at your said premises, the rain water harvesting structure was inspected by NGT Joint Inspection Team on dated 27.03.2019 and found sufficient and adequate to harvest the catchment area of your premises.

You are therefore advised to keep are RWH system neat & clean and maintain the same periodically.

  
EE (RWH/GWC)  
EE (G W CELL)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN,  
JHANDEWALLAN, N.D.-05